

Revitalizing the Sacral Complex of the Parish of the Sacred Heart of Jesus in Gdynia: A Comprehensive Restoration Project in Alignment with Monument Conservator's Guidelines and Technical Prerequisites

Maciej NIEDOSTATKIEWICZ^{*1}, Jacek BRAMORSKI^{2,3}

¹ Department of Engineering Structures, Faculty of Civil and Environmental Engineering,
Gdańsk University of Technology, Gdańsk, Poland

² Parish of the Sacred Heart of Jesus in Gdynia, Gdynia, Poland

³ Church Music Department Faculty of Choral Conducting, Church Music, Artistic Education,
Rhythmics and Jazz Academy of Music Stanisław Moniuszko in Gdańsk, Gdańsk, Poland

Abstract

Religious complexes, due to their monumental character, belong to the group of facilities in which carrying out renovation works is difficult. Very often, construction works carried out as part of planned renovation work include not only modernization but also repair works, including those related to the reinforcement of structural elements. Renovation work in sacral buildings is particularly difficult when they are located in the area covered by conservation. The paper is a case study of the existing religious complex of the Parish of the Sacred Heart of Jesus located in Gdynia, consisting of a church building and a bell tower. The church building realized in the 1960s and the belfry located in its immediate vicinity built in the 1980s after many years of use showed not only signs of operational decapitalization which lowered their aesthetic value as a monument containing elements of modernist architecture, but also all were characterized by damage to construction and finishing elements, which posed a threat to the safety of the structure and use.

Keywords: renovation, modernization, sacral buildings, conservation's requirements

1. Introduction

Sacral complexes, due to their monumental character, belong to the group of objects where it is difficult to carry out renovation works. Very often, construction works carried out as part of planned renovation works include not only modernization works, but also repair works, including those related to strengthening structural elements. Conducting renovation works in sacral buildings is particularly difficult when they are located in an area under conservation protection.

The paper is a case study of the existing Sacral Complex of the parish of Sacred Heart of Jesus (so called: NSPJ in Polish, SHoJ in English) located in Gdynia, and consisting of a church building, a rectory building and a belfry tower. The church building, the construction of which was completed in the early 70s of the twentieth century, and the reinforced concrete belfry tower located in its immediate vicinity, built in the 80s of the twentieth century, after many years of use, not only showed signs of exploitation depreciation, which lowered their aesthetic value as monuments containing elements modernist architecture, but locally they were also characterized by damage to structural and finishing elements, which in the absence of commencement of repair work created a potential threat to the safety of the structure and safety of use.

The paper presents a description of the technical condition of the church building and the bell tower adjacent to it after many years of operation, including the impact of the current use of the buildings and the impact of the scope of renovation works carried out in the past period on their technical condition. The impact of the technical solutions applied during the implementation period on the current limitations related to the modernization of the complex of the sacral building of the parish of the Sacred Heart of Jesus in Gdynia. The implemented technical solutions for the

* **Corresponding author:** E-mail address: (mniedost@pg.edu.pl) Maciej NIEDOSTATKIEWICZ

renovation and modernization of the Sacral Complex were presented, taking into account its historic character and including: renovation of the bell tower, presbytery covering, roof, stone cladding of the wall at the main entrance, revitalization of the plinth, cleaning of the facade and works related to the installation of underfloor heating in the church .

2. History of the Parish of the SHoJ in Gdynia

In the first years after Poland regained independence in 1918, Gdynia belonged to the parish in Oksywie. In 1924, the newly built church at ul. Świętojańska St. Blessed Virgin Mary Queen of Poland, and in 1926 Gdynia was excluded from the parish of Oksywie and an independent parish was created. Soon, however, this newly built church (now the Basilica of the Blessed Virgin Mary, Queen of Poland) turned out to be insufficient for the growing population. It was then that a decision was made to build a branch church at ul. Stefan Batory. The author of the project, covering both the architectural and construction industries, was Eng. Bernard Dulny of Kartuzy. This church, which was named the Sacred Heart of Jesus was put into use in 1929.

Military action in September 1939. did not damage the church. During the German occupation, the church building was not damaged either. Throughout the war, in the years 1939 - 1944, masses were held in the church and services were held in accordance with the liturgy of the Roman Catholic Church.

In the winter of 1945 During the retreat of the Nazi troops from Gdynia, an incendiary bomb fell on the church. The fire completely destroyed the temple building. Thanks to the generosity of parishioners in 1948, In the place of the destroyed one, another church building was built and put into use, part of the external walls of which were made as the so-called half-timbered wall, i.e. a wooden post-and-beam structure with ceramic brick infill. The author of the project covering the architectural and construction industries was mgr inż. Waclaw Rembiszewski. This church could accommodate up to 4,000 people, but the church authorities obtained permission to use it for only 5 years.

January 1, 1949 Bishop of Chełmno, Fr. Kazimierz Kowalski established an independent parish of St. Sacred Heart of Jesus, and its first pastor was appointed Priest Hilary Jastak, who was entrusted with the mission of building a new church.

3. Construction of the Buildings of the Sacral Complex of the Parish of SHoJ in Gdynia

A serious organizational problem in the work of the parish was the lack of social and economic facilities for priests, nuns and civilian employees. In the spring of 1952 the then authorities issued a building permit for the presbytery. Construction works related to the construction of the presbytery were repeatedly suspended as a result of inspections carried out by state authorities (militia, Public Security Office). During the construction, it was repeatedly suggested that the design of the presbytery building should be changed, arguing that it was often invented, non-existent regulations and requirements.

In 1956, on the wave of the so-called After the thaw after the death of Joseph Stalin, preparations for the construction of a new church began quickly. The development of the architectural design was undertaken by prof. arch. Jan Borowski and prof. PhD Eng. Arch. Leopold Taraszkiewicz (Fig.1). According to the idea of Priest Jastak, the newly designed church was to refer to the unrealized idea of building the Maritime Basilica in Gdynia, which, according to pre-war concepts, was to be located on Kamienna Góra. There was even a very intensive search for the foundation stone of the Maritime Basilica, consecrated in 1934, which was to be moved under the building tower of the new church. The available archival materials clearly indicate that these activities were not favorably perceived by the then authorities - there was no political consent for these activities.

In the spring of 1957 The Provincial National Council approved the initial design of the church. In July 1957 all of the projects were approved by the Presidium of the Gdynia National Council and permission was obtained to start construction works. The new church was to be erected in the place of the old one, therefore the construction had to be carried out in stages, so that the liturgy could be celebrated in one part of the old church, and demolition works were carried out in the other. The parishioners were largely involved in the construction work.


The lower church was built first and was consecrated on June 10, 1959. and only then began the construction of the upper church, which was put into use in a raw state in December 1961. For five years, finishing works were carried out, including plastering, assembly of the organ and construction of the altar. a link was also added between the existing presbytery and the newly built church, thanks to which additional apartments were acquired.

The church was consecrated on October 31, 1966. as part of the celebration of the 1000th anniversary of Christianity in Poland.


After 1966, construction works continued, related to the execution of external facades. In 1972, a mosaic was created on the main wall of the presbytery and construction of the choir began.

The construction of the belfry tower (campanilla) lasted the longest, which started in 1973 and was completed in 1981.

a)



b)



c)




Fig. 1: Church of the SHoJ in Gdynia - horizontal projection: a) ground floor, b) high ground floor, c) vertical section (based on archival design documentation)

In May 1988 design documentation for the presbytery superstructure was developed. The author of the architectural design was PhD Eng. Arch. Mirosław Bartoszewicz, while the author of the design for the construction industry was Eng. Stanisław Bartoszewicz. After developing the design documentation and obtaining the relevant administrative decisions, the construction of the superstructure began immediately.

Currently, the Sacral Complex of the parish of SHoJ in Gdynia consists of the following facilities:

- the church building with facilities,
- rectory building,
- bell tower.

4. Architectural Prototype of a Contemporary Parish Church

The architectural prototype of the contemporary parish church, commonly referred to as the SHoJ in Gdynia was a block of the never realized Maritime Basilica. The idea of its construction was born in the early 1930s. The author of the concept of building the Basilica was priest PhD Stanisław Wojciech Okoniewski, Bishop of Chełmno. The basilica

was planned to be located directly on Kamienna Góra. Thanks to this location, it was supposed to be a visible symbol of the city from afar. In order to implement this idea, the Society for the Construction of the Maritime Basilica was established.

The building was to have the form of a three-aisle basilica crowned with a system of 3 towers growing on a common nave, symbolizing the 3 partitions connected after Poland regained independence. In the form of a complex of 3 towers, the maritime symbol of the basilica was to be included - the shape of a three-masted ship (Fig.2).




Fig. 2: Maritime Basilica in Gdynia - conceptual design: a) front elevation and projections, b) location on Kamienna Góra (based on [G1])

The project of MSc Eng. Arch. Bohdan Pniewski, who was the author of the winning study in the announced nationwide competition for project documentation. The construction of the Maritime Basilica began in 1934, when, during the Festival of the Sea, priest PhD Stanisław Wojciech Okoniewski consecrated the foundation stone. The ceremony was graced by the presence of the President of the Republic of Poland, Ignacy Mościcki.

Immediately after the start of construction, the problem of the subsoil bearing capacity arose: the available archival materials indicate that the area where the foundations had already been partly laid was not at the stage of preparing the structural design, which was carried out in a simplified form, which was characteristic of investments carried out at that time, sufficiently explored in terms of geological structure.

Problems with the safe foundation of the building resulted in a new concept for the location of the Maritime Basilica - this time it was to be built at the foot of Kamienna Góra. Work on the new project was interrupted by the outbreak of World War II in September 1939.

5. The Technical Condition of the Buildings of the Sacral Complex of the Parish of SHoJ in Gdynia

Intensive renovation works of the buildings of the Sacral Complex of the parish of SHoJ in Gdynia have been conducted since 2015. Earlier works were temporary and protective repairs. Renovation and repair works are carried out on the basis of repair documentation prepared each time, the degree of accuracy of which is adapted to the nature

of these works. Due to the location of the objects in the conservation protection zone, construction works are carried out in agreement and with the approval of the Municipal Conservator of Monuments.

The scope of the renovation works carried out so far included recommendations on how to assess the technical condition of buildings [A1] - [A21].

The developed programs of repair works also took into account the cases of defects and damage to structural systems [B1] - [B31] described in the literature.

The repair documentation also included information on pre-failure states, failures, as well as the operation, renovation and modernization of historic buildings, including historic sacral buildings [C1] - [C55].

Particular emphasis, due to the proximity of the communication system, both road and railway, was placed during the analysis of the scope of renovation works for individual objects on the negative impact of vibrations on structural systems [D1] - [D16]. At the same time, there were no visible faults and damages on the structural and finishing elements of the buildings of the Sacred Complex, the morphology of which would indicate a negative impact of the nearby communication systems. Since no perceptible vibrations of the ground around the buildings of the Sacral Complex have ever been found, measurements of ground vibrations were abandoned, assuming that their results would not bring significant information for further analysis of their technical condition and planning renovation works.

The scope of repair works developed each time took into account the aspects related to the deformation of the subsoil as well as the methods and manner of securing buildings located in areas characterized by complex foundation conditions [E1] - [E20]. The objects of the Sacral Complex did not show external signs indicating their excessive subsidence.

During the construction of the buildings of the Sacred Complex, no trees with a significant trunk or crown size were removed from the adjacent area. Also, no new tall-stem trees and shrubs were planted. Thus, there were no grounds to conclude that the root system of the existing stand will have an impact in the future on the occurrence of faults and/or damage to the foundations of the buildings of the Sacral Complex, which in turn could damage their structure, as well as to formulate a thesis that the roots of the stand will contribute to disturbance of ground and water conditions in the area around these facilities [F1] - [F4].

In addition, the paper uses information on the implementation of the buildings of the Sacral Complex of SHoJ in Gdynia [G1] - [G4].

6. Renovation and Repair Works of the Buildings of the Sacral Complex of the Parish of SHoJ in Gdynia - Selected Examples

Renovation of the bell tower

Church bell tower SHoJ was implemented on the basis of socially developed project documentation (Photo 1). The author of the architectural design was MSc Eng. Arch. Julian Demczuk, while the author of the structural design was MSc Eng. Henryk Płociński. The function of the structural design verifier was performed by MSc Eng. Władysław Buczkowski. The spatial, openwork structure of the tower was designed and made as reinforced concrete, monolithic, made of concrete class $R_w=170$ atm., reinforced with ribbed steel bars A-III class 34GS (structural reinforcement) and smooth bars made of A-0 steel, St0 mark (stirrups). In cross-section, the tower has the shape of an equilateral triangle, in the corners of which there are reinforced concrete, monolithic columns with a V-shaped cross-section (pole designation: A, B, C) (Fig.3).




Fig. 3. The bell tower of the Church of the SHoJ in Gdynia - cross section




Photo 1. The bell tower of the Church of the SHoJ in Gdynia: a) general view, b) close-up of the internal staircase (photo by Maciej Niedostatkiewicz)

The columns at the height are connected with horizontal, reinforced concrete transoms located at the height of the tower in 6 levels: level 1 at a height of +6.00 m above sea level, level 2 at a height of +12.00 m above sea level, level 3 at a height of +18.00 m above sea level, level 4 at +24.00 m above sea level, level 5 at +30.00 m above sea level and level 6 at +36.00 m above sea level. In the cross-section, the bolts had the shape of a rectangle measuring 40×45 cm. The spaces between the transoms (from level 1 to level 5) were filled with decorative prefabricated reinforced concrete posts, which are set on horizontal transoms. The number of posts set on one transom (side) is 6 pcs. The posts in the cross-section had the shape of a rectangle with dimensions of 15×30 cm, the axial spacing of the posts was 25 cm. In the middle of the tower, reinforced concrete, prefabricated screw and column stairs were made, enabling the belfry staff to climb to the top of the tower. The load-bearing element of the stairs is a reinforced concrete monolithic column on which the prefabricated steps were mounted (prefabricated step plates with an opening constituted the formwork of the monolithic load-bearing column). From level 6 (+36,00 m above sea level), a steel structure of the spire was made of profile steel covered with copper sheet. The total height of the tower is +62.00 m above sea level. A bell with a weight of 2.5 t is suspended from the structure in the technical level no. 6. The tower was placed directly on the ground at the level of -3,0 m below ground level. on a circular, reinforced concrete, monolithic foundation plate with a diameter of 10,8 m. In the places where the columns rest, a circumferential ring was constructed on the plate, from which the reinforcement of the columns was led. Up to level 1 (+ 6.0 m above sea level), reinforced concrete walls of the ground floor casing were made on the ring. The thickness of the foundation slab under the columns was 2,0 m (thickness of the slab with the perimeter ring), in the remaining part the slab was 1,0 m thick. At the foundation level, there were non-cohesive soils - medium sands (Ps).

The construction of the tower was carried out in an economic way, as a result of which it was carried out with many imperfections, among others, it was characterized by the lack of verticality of some column elements and the lack of proper cover of the reinforcement bars. The construction of the tower was assumed to have the texture of raw concrete. At the execution stage, the concrete surface was not protected in any way against weather conditions, which over many years of concrete exposure to the harmful effects of aerosols containing salts, including those from sea water, led to extensive corrosion of the concrete. Progressive carbonation combined with frost damage to the concrete resulting from moisture caused, among others, by the lack of flashing of reinforced concrete elements, led to damage to the concrete cover of the reinforcement bars. At individual levels (from 1 to 6) no cracks or cracks of mullions and

transoms were found. On the other hand, there was massive loosening of the cover of the main reinforcement and stirrups as a result of corrosion of the bars and stirrups (Photo 2, Photo 3 and Photo 4).




Photo 2. Examples of damage to reinforced concrete, monolithic columns of the belfry tower: a), b), c) detachments and losses of the concrete cover and corrosion of the reinforcement bars (photo by Maciej Niedostatkiewicz)




Photo 3. Examples of damage to the monolithic reinforced concrete bolts of the belfry tower: a), b), c) losses of the concrete cover and corrosion of the reinforcement bars (photo by Maciej Niedostatkiewicz)




Photo 4. Examples of damage to the reinforced concrete prefabricated pillars of the belfry tower: a), b), c) losses of the concrete cover and corrosion of the reinforcement bars (photo by Maciej Niedostatkiewicz)

Corrosion damage at levels 4-5 and 5-6 was more intense than at levels 2-3 and 3-4. Occurring damage to the tower made it necessary to shut down the carillon, which had been operating continuously for almost 35 years, due to the danger of moving around the internal staircase in order to activate the bell. Vertical cracks were visible on the column formed from the assembly of prefabricated stairs, in the section between levels 2-3 (Photo 5).



Photo 5. Outlined, in the line of the axial anchorage, prefabricated steps of the spiral stairs leading to the top of the belfry tower (photo by Maciej Niedostatkiewicz)

The assessment of the technical condition of the bell tower included the analysis of the results of: a) concrete pH tests, b) sclerometric tests and c) static and strength calculations.

pH testing

The most popular, but at the same time the least accurate method of estimating the depth of carbonation in hardened concrete is the phenolphthalein method, described in detail in [N7]. Standard regulations and technical literature recommend that the color change of the non-carbonated zone be measured within 30 seconds of wetting with the solution. It should be emphasized that the color change of the concrete fracture from colorless to red-violet occurs at

$pH \approx 9,0$. At a pH value of 11,8, concrete loses its natural ability to protect steel against corrosion, and at a pH value of $<11,2$, corrosion processes are initiated on the steel surface. Using the phenolphthalein method to determine the extent of the carbonation front, it is possible to significantly overestimate the extent of the zone of reduced protective properties of concrete in relation to the reinforcement. More accurate measurement results are obtained by using liquids (reagents) dedicated to concrete to determine the depth of concrete carbonation. In the case of the church belfry tower, the measurement solution of Germann Instruments, the so-called Rainbow Test (Fig.4). The measurement consisted in spraying a liquid solution on the concrete surface (fresh break of the sample taken), which changed its color depending on the pH value of the concrete. The assessment of the depth and degree of carbonation was made by comparing the color of the sprayed sample (Photo 6) with the template (Fig. 4). The transition of the color palette from violet ($pH \approx 11$) to green ($pH \approx 9$) signals a decrease in pH below the value considered as the limit value and signals a potential corrosion threat to the reinforcement (Fig.4):

- 11-13 - concrete free from carbonation effects,
- 11 - limit value (reduced cover ability to protect reinforcement against corrosion),
- $\downarrow 9$ (< 9) - reinforcement corrosion hazard,
- $\downarrow 7$ (< 7) - corrosion of reinforcement bars.



Fig. 4. Concrete discoloration chart for the control liquid - Rainbow Test (based on materials from Germann Instruments)




Photo 6. Exemplary results of measurements of the degree of concrete carbonation in the performed open pits: a) and b) discoloration of concrete on the main pillars of the bell tower from $pH=5$ to $pH=11$ and c) discoloration of the forged fragment of the concrete cover of the transom reinforcement bars from $pH=5$ to $pH=13$ (photo by Maciej Niedostatkiewicz)

Based on the tests performed, the results were obtained, below are representative results:

- pole A3-4 (level 4) $pH = 7$,
- column C3-4 (level 4) $pH = 7$,
- column C2-3 (level 3) $pH = 9$,
- column A1-2 (level 2) $pH = 11$.

The obtained test results allowed to conclude that the concrete in the near-surface zone (cover) lost its ability to protect the reinforcement bars against corrosion [N7]. In the excavations, corrosion of the reinforcement bars was found: the measured corrosion losses of the bars were up to 2 mm in diameter of the main reinforcement bars and up to 1.50 mm in diameter of the transverse reinforcement bars (stirrups).




Photo 7. Reinforced concrete belfry tower during renovation works: a) general view, b), c) close-up details of the scaffolding (photo by Jacek Bramorski)

Sclerometric examinations

Due to the insufficient technical condition of the spiral stairs, the collection of concrete samples for destructive testing using a drilling rig was abandoned. In order to estimate the strength of concrete, a number of comparative sclerometric tests were performed [N6].

The testing of concrete in columns and transoms at individual levels (from No. 1 to No. 6) was carried out using a non-destructive method using a Schmidt type N hammer. All measurements were made on exposed concrete after grinding its surface with a high-speed grinder.

The following results were obtained during the tests:

- a) columns (results averaged over the entire height of the column (levels 1-6):
 - column A: $f_{c,cube}=20.90$ MPa, sufficient homogeneity,
 - column B: $f_{c,cube}=23.00$ MPa average homogeneity,
 - column C: $f_{c,cube}=19.10$ MPa average homogeneity.
- b) bolts (exemplary results for selected bolts):
 - R2 transom, level 2, between columns B-C: $f_{c,cube}=24.60$ MPa, medium homogeneity,
 - R3 transom, level 3, between columns B-C: $f_{c,cube}=25.40$ MPa good homogeneity,
 - R4 transom, level 4, between columns B-C: $f_{c,cube}=34.10$ MPa, sufficient homogeneity,
 - R5 transom, level 5, between columns B-C: $f_{c,cube}=21.90$ MPa, sufficient homogeneity.

In the available archival design documentation, it was assumed that the tower structure would be made of concrete of the $R_w=170$ atm class, which roughly corresponds to the B15 (C15/20) concrete class. The obtained test results showed that the concrete in the columns and transoms of the tower had a higher compressive strength than assumed in the design, but it was characterized by high heterogeneity.

Verifying static and strength calculations

Based on the analysis of the available archival design documentation, the following was established:

- at the stage of static and strength calculations, the spatial layout was simplified to a flat frame,

- nomograms (approximate method) were used to design reinforced concrete elements with a triangular cross-section,
- due to the monumental nature of the structure, the principle of increasing the cross-section of vertical reinforcement in the tower columns by 50% (columns in the A, B and C axes) was adopted,
- a bell with a mass of 5.00 t was assumed for the calculations.

Verifying static and strength calculations were made for the following parameters (assumptions):

- analysis of a bar spatial model (3D) using a program based on the finite element method (FEM),
- dimensioning of reinforced concrete sections was carried out according to the rules set out in [N1] - [N4], [N8],
- the exact (real) distribution of stresses in the cross-section for the triangular columns of the tower in the axes A, B and C was taken into account,
- during the calculations, the actual corrosion losses of the main reinforcement bars were taken into account, assuming bars with a diameter smaller by 2 mm in relation to the nominal diameter,
- a bell with a mass of 2,50 t (implemented solution) was adopted for the calculations instead of 5.00 t as in the designed state.

The results of the calculations showed that the structure of the belfry tower does not pose a threat to the safety of the structure, safety of use and that there is no risk of losing the stability of the tower as a whole. The maximum determined effort level for the main columns was 47%, and for the horizontal girders - 54%.

Construction works related to the renovation of the belfry tower were carried out in the following scope:

- structural elements (main columns in the axes A, B, C, prefabricated auxiliary posts, as well as transoms and beams at the level of technical platforms from 1 to 6) were reprofiled with the use of PCC and PCC II repair compounds,
- scratches on the column of the spiral stairs between levels 2-3 were secured by the use of adhesive injection. It was assumed that if the cracking of the column reappeared, it would be necessary to strengthen it and protect it by gluing carbon mats, creating the form of closed rings around the column between the prefabricated steps of the stairs,
- after the reprofiling, the surfaces of the reinforced concrete elements were covered with hydrophobing agents that minimize the migration of moisture and compounds contained in the air into the concrete, at the same time minimizing the progress of concrete carbonation.

The repair works of the reinforced concrete belfry tower were carried out in accordance with the requirements specified in [N5].

Renovation of the chancel roof

Due to the leaks occurring for many years inside the church, the so-called renovation works were carried out. lighthouse located above the presbytery of the so-called upper church.

The scope of renovation works included the disassembly of the existing glazing (single glazing), reprofiling of the so-called concrete joinery constituting a grid for glazing and re-assembly of small-sized elements of glass panes. As part of the repair work, painting work was also carried out in the inner part of the tower.

Carrying out renovation works required the construction of scaffolding with intermediate working platforms, enabling the repair of windows at different levels of the lighthouse. The built scaffolding, the base of which was placed in the presbytery (Photo 8), was convergent upwards and adjusted to the inclination of the outer walls of the lighthouse. The erection of the scaffolding was made on the basis of the developed design documentation, taking into account the need to stamp the ceiling above the basement in the area of the presbytery room.






Photo 8. Preparatory works for the renovation of the presbytery cover: a), b) scaffolding assembly (photo by Jacek Bramorski)

Roof repair

Renovation of the roof over the central (central) nave, the so-called the construction of the upper church was the next stage of the long-term scope of renovation works. As part of the repair work, local repairs were made to the cracked plaster of the base of the lantern above the presbytery, locally the plaster was replaced with a new one, with the structure of the so-called cyclins (Photo 9).






Photo 9. Roof of the Church of the SHoJ in Gdynia: a) general view towards the so-called lantern over the presbytery, b) cracks in the plaster of the lantern plinth, c), d) cracks in the plaster of the attic along the lantern, flashings of the attic along the lantern: e) before and f) after the replacement (photo by Maciej Niedostatkiwicz and Jacek Bramorski)

The renovation works also included the replacement of the existing, intensively depreciated flashings. The main scope of renovation works on the roof over the central nave included reprofiling the reinforced concrete gable beams of the roof slopes - the beams had numerous corrosion damages, the concrete cover of the reinforcement bars was falling off and extensive moisture damage was visible (Photo 10). The repair works included the reprofiling of reinforced concrete elements with the use of PCCI and PCC II repair compounds, taking into account the use of passivating materials for corroded reinforcing bars. The scope of renovation works also included the replacement of flashings and flashings of the roof slopes and the replacement of existing downpipes.

As part of the repair work on the reinforced concrete elements of the roof slope above the central nave, the reinforced concrete beams supporting the cross placed on the roof, visible from the side of the front façade, were also reprofiled (Photo 11).






Photo 10. Shed roof over the nave of the Church of the SHoJ in Gdynia: view: a) general, b) close-up, c), d), e), f) examples of damage to the roof cornice (photo by Maciej Niedostatkiwicz)



Photo 11. Reinforced concrete, monolithic beams of the grate supporting the cross from the west elevation (along 3 Maja Street) - condition: a) before, b) after renovation (street names as of 2023) (photo by Maciej Niedostatkiwicz)

Works related to the renovation of the roof were carried out on the basis of the developed repair documentation, which took into account the selection of materials for the reprofiling of reinforced concrete elements in accordance with the requirements specified in [N5].

Renovation of the stone cladding of the wall at the main entrance

Renovation of the stone cladding of the wall at the main entrance was another stage of the renovation works of the Church of the SHoJ in Gdynia. The wall constituting the outer partition of the rooms located in the lower level of the church had a cladding made of pebbles, some of which were split. The cladding, made at the turn of the 1960s and 1970s, looked like a wall made of natural stones, locally made as a wild wall (made of unsplit stones), with local redecoration as a cyclopean wall (made of split stones). Machined stones were used in particular in lintel bands and in convex corners (Photo 12). The cladding was built on a fine-grained cement mortar, at the stage of its implementation, no elements were used to anchor the stone cladding with the structural wall made of stainless steel or galvanized steel. Also, no horizontal relief shelves were made at the height of the wall, no vertical or horizontal expansion joints were used. The foundation of the wall was made on the widened footing of the external wall.

Over the years of operation, the stone cladding underwent natural decapitalization - the joints underwent carbonation, pores opened in them and capillaries through which water began to penetrate into the space between the cladding and the wall. In the middle of the height of the wall, the cladding was scratched, its lower part was buckling. The stability of the cladding was preserved thanks to its inclination in the direction "from the street", which was ~ 100.



Photo 12. Damage to the stone cladding of the wall at the entrance from the west elevation (along 3 Maja Street): a), b), c), d) wall cracks, e) stone falling out from the outside, f) cracks from the inside (street names as of 2023) (photo by Maciej Niedostatkiewicz)

Decorative elements made on the cladding - religious symbols in the form of a heart and a cross and the date (year of completion of the construction of the Church) have not stratified over the years of operation (Photo 13), but it was noted that the date is detached from the structural wall.

As part of the renovation works, the cladding was dismantled, locally down to the foundation level (Photo 14a), its stable fragments were left along part of the length of the wall. The cladding was rebuilt with recovered stones, after their prior mechanical cleaning and bathing in a paste solution with the addition of ammonium fluoride. A vapor-permeable, low-shrinkage packaged mortar with a reduced amount of lime was used to build the stone cladding. The laying of the cladding was preceded by the implementation of anti-moisture insulation on the footing and on the outer wall in the ground zone (Photo 14b). The insulation was made of a mineral mortar based on polymer-modified microsilica. As part of the work related to the execution of insulation, a facet was profiled at the junction of the continuous footing and the structural wall.

As part of the renovation works, the terrazzo cap of the wall was also renovated: existing cracks were furrowed, repaired with a filling injection, and after mechanical grinding of the terrazzo cap, a protective hydrophobic coating was applied on its upper and side surfaces.




Photo 13. Characteristic symbols made in the stone cladding of the wall from the west elevation (along 3 Maja Street): a) heart, b) cross, c) 1969 (year of completion of the construction of the church) (street names as of 2023) (photo by Maciej Niedostatkiwicz)



Photo 14. The wall at the entrance from the west elevation (along 3 Maja Street) during renovation works: a) dismantled cracked stone cladding and implementation of vertical damp-proof insulation, b) repaired cracks in the terrazzo cladding of the wall cap (names of the street as of 2023) (photo by Jacek Bramorski)

Works related to the renovation of the stone cladding were carried out on the basis of the developed renovation documentation, which took into account the selection of materials in accordance with the conservation guidelines.

Revitalization of the plinth

The plinth of the church building consisted of two parts: the lower one in the form of a cladding made of pebbles and the upper one made of plaster dyed in the mass (Photo 15).



c)

d)



Photo 15. Base cornice after completion of renovation works: a), b) along the western elevation (from the side of 3 Maja Street), c) from the southern elevation (along Armii Krajowej Street), d) along the eastern elevation (from the side of Monsignore Hilarego Jastaka Street), e), f) from the northern elevation (along Stefana Batorego Street) (street names as of 2023) (photo by Maciej Niedostatkiwicz)

The lower part had damage similar to damage to the stone cladding of the wall at the main entrance. The stones were dirty, covered with a coating. Single stones were loosened, some of the joints were chipped. As part of the renovation works, the entire surface of the lower part of the plinth was first wetted with water at a temperature of $\sim 30^{\circ}\text{C}$, and then a thin layer of ammonium fluoride-based cleaning paste was applied to the surface of the plinth using a bench brush and the plinth was again washed with warm water. After cleaning, loose stones were glued in, and then the jointed stone cladding was supplemented with the materials used to repair the stone cladding of the wall at the main entrance.

The upper part of the plinth had damages in the form of plaster burns from the concrete base, the entire surface of the plaster was discolored and faded. As part of the renovation work, the scalded plaster was chipped off and restored. The new plaster was made as a layered plaster, with a primer layer and a top layer, after prior priming of the substrate and making a bond bridge. The top layer of the plaster was made as colored in the mass, with the use of fine quartz aggregate, with the use of a trass mortar dyed in the mass. The newly made external plaster on the plinth was made as rubbed plaster, with a structure matched to the structure of the plaster fragments left. After the local plaster repairs were completed, its entire surface was secured with an additional protective paint coating, in accordance with the conservation guidelines - a silicone facade paint was used, characterized by high water vapor diffusivity. As part of

the repair work, the flashings on the upper surface of the plinth were also replaced. The original flashings were made of zinc sheet, joined with the use of reflected and smooth coils, they were replaced with flashings made of steel-titanium sheet joined with standing seams.

Facade cleaning

The next stage of the renovation works of the Church building was the cleaning of the elevation (Photo 16). All facades of the building were subjected to restoration works, which were cleaned using the hydromonitoring method (Photo 17), using hot water at a temperature of 30°C. As an addition to the purification, an agent with a neutral pH was used, containing surfactants, i.e. surfactants that lower the surface tension of water. Thanks to the emulsifying properties of the agent used, the washed dirt and impurities were bound, especially the layer of grease and dust accumulated over the years of operation on the surface of the plaster made as the so-called. scraper. After cleaning, the facades were not additionally secured with a protective paint coating with the addition of anti-algae and anti-fungal agents, it was assumed that the protection would be provided by preservatives used in the production of the detergent in order to obtain its durability.



Photo 16. Church facades during their cleaning: a) western (from the side of 3 Maja Street) and b) eastern (from the side of Monsignore Hilarego Jastaka Street) (street names as of 2023) (photo by Jacek Bramorski)



Photo 17. Comparison of the structure and color of the facade a) before and b) after its cleaning - on the example of the eastern facade (from the side of Monsignore Hilarego Jastaka Street) (street names as of 2023) (photo by Jacek Bramorski)

Works related to the installation of underfloor heating in the church

Underfloor heating has been installed in the so-called upper church. Loops with a heating medium were arranged under three rows of benches - the installation of underfloor heating did not require changing the arrangement of the benches, functioning in the so-called the upper church in an unchanged form until it is made available to the faithful. The implementation of the water-type underfloor heating was carried out on the basis of a design study - an executive design. During the works related to the installation of underfloor heating, special attention was paid to the fact that the thickness of the layers of thermal insulation material and the concrete screed was selected in such a way as to protect the heating installation against the possibility of heat loss (thickness of the thermal insulation material) and the possibility of damage to the heating loops (thickness of the concrete screed (anhydrite)), on the other hand, so that the installation of underfloor heating does not make it necessary to rebuild (raise) the existing platforms under the benches. The heating center was installed on the level of the upper church. The individual stages of work related to the installation of underfloor heating in the so-called the upper church is shown in Photo 19.




Photo 18: The condition of the facade from the south (along Armii Krajowej Street) after cleaning: a) view of the facade plaster, b) concrete window frames after revitalization (name of the street as of 2023) (photo by Jacek Bramorski)






Photo 19: Installation of underfloor heating in the Church of the SHoJ in Gdynia in the rooms of the so-called of the upper church: a), b), c), d), e), f) stages of work (photo by Jacek Bramorski)

7. Conclusions

Despite the further rapid development of civilization, traditions, including those related to building customs, should be respected. Tradition is an intangible value, it is completely incalculable, but it determines the quality of life in a very significant way.

Superstitions and the consequent building habits should be approached reasonably, it is impossible to lead to a situation where irrational premises will determine the quality of life, limiting the possibility of conscious decision-making.

Nowadays, the most popular are the superstitions and customs related to the construction of the building and the start of living in it. The most popular, belonging to the first group, is the custom of hanging a topping out (wreath) after the end of the so-called shell of an open building. Also common is the custom of a celebration after moving into a building, commonly referred to as a housewarming party, belonging to the second group of superstitions and customs used in the construction industry.

During the period of operation, elements of the Sacral Complex of The NSPJ in Gdynia has been rebuilt and modernized many times.

Each time, the scope of renovation and repair works took into account the historic nature of the buildings.

Due to the cyclical construction works carried out on the premises, due to the current technical condition, none of the elements of the Sacred Complex show a direct threat to the safety of the structure and safety of use.

Church of Sacred Heart of Jesus in Gdynia has recently been recognized as one of the best-kept monuments in Poland. June 20, 2023 in Warsaw, was the winner of the "Well-kept Monument" competition in the category "Preservation of the historic value of the building".

"Well-kept Monument" is a prestigious competition of the Minister of Culture and National Heritage, on whose behalf the General Conservator of Monuments is responsible, and the National Heritage Board of Poland is responsible for the competition procedures. It has been organized for over half a century in order to promote historic buildings, where construction, conservation, restoration and adaptation works are carried out in an exemplary manner, as well as systematic actions for their proper maintenance in accordance with the highest research and executive standards.

References

- A1 Baranowski W.: Zużycie obiektów budowlanych. *Wydawnictwo Warszawskiego Centrum Postępu Techniczno-Organizacyjnego Budownictwa, Ośrodek Szkolenia WACETOB sp. z o.o.*, Warszawa, 2000.
- A2 Baryłka A., Baryłka J.: Diagnostyka techniczna obiektu budowlanego. *Budownictwo i Prawo*, Warszawa, 19-22, 4, 2015.
- A3 Drobiec Ł.: Techniki diagnostyczne i sprzęt umożliwiające badania obiektów budowlanych. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 241-259, Cedzyna, 2022.
- A4 Drozd W.: Analiza katastrof budowlanych w Polsce w latach 2004-2019. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 187-198, Szczecin - Międzyzdroje, 2022.
- A5 Halicka A.: Ocena istniejących konstrukcji budowlanych według normy ISO 13822-2010. *V Ogólnopolska Konferencja Problemy techniczno-prawne utrzymania obiektów budowlanych*. Warszawa, 2019.
- A6 Hoła J., Runkiewicz L.: Zasady wykonywania ekspertyz konstrukcji żelbetowych. *Wydawnictwo Naukowe PWN*, Warszawa, 2020.
- A7 Kucharska-Stasiak E.: Metody pomiaru zużycia obiektów budowlanych. *Materiały Budowlane*, Warszawa, 2, 29-38, 1995.
- A8 Mazur M.: Prawa i obowiązki uczestników procesu budowlanego przy naprawach i wzmocnieniach konstrukcji w świetle Ustawy Prawo budowlane i rozporządzeń wykonawczych. *XXXVII Ogólnopolska Konferencja Warsztat Pracy Projektant Konstrukcji WPPK-2023*, 31-58, Wisła, 2023.
- A9 Niedostatkiewicz M., Majewski T.: Diagnostyka uszkodzeń żelbetowej, monolitycznej ściany w realizowanym budynku wielorodzinnym. *Materiały Budowlane*, Warszawa, 11, 603, 1-5, 2022.
- A10 Obolewicz J., Baryłka A.: Interpersonal communication in construction management engineering. *Inżynieria Bezpieczeństwa Obiektów Antropogenicznych*, 1, 39-45, Warszawa, 2022, <https://doi.org/10.37105/iboa.131>.
- A11 Piekarczyk A.: Wykrywanie wad struktury oraz lokalizacja zbrojenia w konstrukcjach żelbetowych metodami nieniszczącymi. *XXXVII Ogólnopolska Konferencja Warsztat Pracy Projektant Konstrukcji WPPK-2023*, 525-604, Wisła, 2023.
- A12 Runkiewicz L.: Przyczyny powstawania zagrożeń, awarii i katastrof obiektów budowlanych. *Przegląd Budowlany*, Warszawa, 91, 5, 48-49, 2020.
- A13 Runkiewicz L.: Wybrane przykłady awarii i katastrof obiektów budowlanych w budownictwie ogólnym. *XXXIV Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2019*, Szczyrk, 2019.
- A14 Runkiewicz L., Hoła J.: Diagnostyka techniczna konstrukcji żelbetowych. *Inżynieria i Budownictwo*, Warszawa, 7-8, 397-405, 2018.
- A15 Runkiewicz L., Okuń R.: Stosowanie opracowań rzeczoznawczych w budownictwie. *Przegląd Budowlany*, Warszawa, 90, 5, 48-49, 2019.
- A16 Runkiewicz L., Szulc J., Sieczkowski J.: Metoda diagnostyk, napraw i wzmocnienia obiektów budowlanych o konstrukcji żelbetowej. *XXXVII Ogólnopolska Konferencja Warsztat Pracy Projektant Konstrukcji WPPK-2023*, 227-290, Wisła, 2023.
- A17 Schabowicz K.: Najnowsze metody nieniszczące wykorzystywane w badaniach w budownictwie. *Badania Nieniszczące i Diagnostyka*, 3, 48-51, Warszawa, 2018.
- A18 Srokowski W.: Studia nad metodą określania stopnia zużycia technicznego budynków mieszkalnych. *Wydawnictwo Instytutu Gospodarki Mieszkaniowej*, Warszawa, 1971.
- A19 Substyk M.: Utrzymanie i kontrola okresowa obiektów budowlanych. *Wydawnictwo ODDK*, Warszawa, 2012.
- A20 Szer J., Jeruzal J., Szer I., Filipowicz P.: Kontrole okresowe budynków – zalecenia, wymagania i problemy. *Wydawnictwo Politechniki Łódzkiej*, Łódź, 2020.
- A21 Świt G., Krampikowska A., Tworzewski P.: Wykorzystanie metod NDT do pomiaru i morfologii zarysowań w warunkach in-situ. *XXXVII Ogólnopolska Konferencja Warsztat Pracy Projektant Konstrukcji WPPK-2023*, 369-394, Wisła, 2023.
- B1 Arendarski J.: Trwałość i niezawodność budynków mieszkalnych. *Wydawnictwo Arkady*, Warszawa, 1978.
- B2 Bukowski B.: Morfologia rys w konstrukcjach betonowych i żelbetowych. *Archiwum Inżynierii Lądowej*, 3, 4, Warszawa 1957.
- B3 Drobiec Ł., Jasiński R.: Diagnostyka konstrukcji żelbetowych, tom 1. *Wydawnictwo PWN*, 2010.
- B4 Drobiec Ł., Jasiński R., Piekarczyk A.: Konstrukcje murowe według Eurokodu 6 i norm związanych, tom 1-3, *Wydawnictwo PWN*.
- B5 Lewicki B., Woźniak K.: Ustroje i roboty budowlane. *Państwowe Wydawnictwo Szkół Zawodowych*, Warszawa, 1965.

- B6 Masłowski E., Spizewska D.: Wzmacnianie konstrukcji budowlanych. *Wydawnictwo Arkady*, Warszawa, 2000.
- B7 Mitzel A., Stachurski W., Suwalski J.: Awaryjne konstrukcje betonowych i murowych. *Wydawnictwo Arkady*, Warszawa, 1982.
- B8 Noakowski P.: Rysy w żelbecie jako język konstrukcji. Różne formy zarysowania i ich interpretacje. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 155-173, Cedzyna, 2022.
- B9 Niedostatkiwicz M.: Dachy stropodachy tarasy. Remonty i wzmacnianie. *Polskie Centrum Budownictwa Difin i Muller sp. z o.o.*, 1-178, Warszawa, 2016.
- B10 Praca zbiorowa pod redakcją Kamiński M., Jasiczka J., Buczkowski W., Błaszczyński T.: Trwałość i skuteczność napraw obiektów budowlanych. *Dolnośląskie Wydawnictwo Edukacyjne*, Wrocław, 2007.
- B11 Praca zbiorowa pod redakcją Kamiński M., Jasiczka J., Buczkowski W., Błaszczyński T.: Współczesne metody naprawcze w obiektach budowlanych. *Dolnośląskie Wydawnictwo Edukacyjne*, Wrocław, 2009.
- B12 Rokiel M.: Renowacje obiektów budowlanych. Projektowanie i warunki techniczne wykonania i odbioru robót. *Wydawnictwo Medium*, Warszawa, 2014.
- B13 Sokalska A.: Naprawa i ochrona konstrukcji żelbetowych. *Wydawnictwo Instytutu Techniki Budowlanej*, Warszawa, 2012.
- B14 Ściślewski Z.: Trwałość konstrukcji żelbetowych. *Wydawnictwo ITB*, Warszawa, 1995.
- B15 Ściślewski Z.: Ochrona konstrukcji żelbetowych. *Wydawnictwo Arkady*, Warszawa, 1999.
- B16 Thierry J., Zaleski S.: Remonty budynków i wzmacnianie konstrukcji. *Wydawnictwo Arkady*, Warszawa, 1982.
- B17 Urban T.: Wzmacnianie konstrukcji żelbetowych metodami tradycyjnymi. *Wydawnictwo PWN*, Warszawa, 2015.
- B18 Kobiak J.: Błędy w konstrukcjach żelbetowych. *Wydawnictwo Arkady*, Warszawa, 1971.
- B19 Lewicki B., Woźniak K.: Ustroje i roboty budowlane. *Państwowe Wydawnictwo Szkół Zawodowych*, Warszawa, 1965.
- B20 Masłowski E., Spizewska D.: Wzmacnianie konstrukcji budowlanych. *Wydawnictwo Arkady*, Warszawa, 2000.
- B21 Mitzel A., Stachurski W., Suwalski J.: Awaryjne konstrukcje betonowych i murowych. *Wydawnictwo Arkady*, Warszawa, 1982.
- B22 Noakowski P.: Rysy w żelbecie jako język konstrukcji. Różne formy zarysowania i ich interpretacje. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 155-173, Cedzyna, 2022.
- B23 Niedostatkiwicz M.: Dachy stropodachy tarasy. Remonty i wzmacnianie. *Polskie Centrum Budownictwa Difin i Muller sp. z o.o.*, 1-178, Warszawa, 2016.
- B24 Praca zbiorowa pod redakcją Kamiński M., Jasiczka J., Buczkowski W., Błaszczyński T.: Trwałość i skuteczność napraw obiektów budowlanych. *Dolnośląskie Wydawnictwo Edukacyjne*, Wrocław, 2007.
- B25 Praca zbiorowa pod redakcją Kamiński M., Jasiczka J., Buczkowski W., Błaszczyński T.: Współczesne metody naprawcze w obiektach budowlanych. *Dolnośląskie Wydawnictwo Edukacyjne*, Wrocław, 2009.
- B26 Rokiel M.: Renowacje obiektów budowlanych. Projektowanie i warunki techniczne wykonania i odbioru robót. *Wydawnictwo Medium*, Warszawa, 2014.
- B27 Sokalska A.: Naprawa i ochrona konstrukcji żelbetowych. *Wydawnictwo Instytutu Techniki Budowlanej*, Warszawa, 2012.
- B28 Ściślewski Z.: Trwałość konstrukcji żelbetowych. *Wydawnictwo ITB*, Warszawa, 1995.
- B29 Ściślewski Z.: Ochrona konstrukcji żelbetowych. *Wydawnictwo Arkady*, Warszawa, 1999.
- B30 Thierry J., Zaleski S.: Remonty budynków i wzmacnianie konstrukcji. *Wydawnictwo Arkady*, Warszawa, 1982.
- B31 Urban T.: Wzmacnianie konstrukcji żelbetowych metodami tradycyjnymi. *Wydawnictwo PWN*, Warszawa, 2015.
- C1 Bartnik G., Bukowski M.: Analiza przyczyny spękań Kościoła parafialnego Św. Rocha w Jazgarzewie. *XXIII Konferencja Naukowo-Techniczna Awaryjne Budowlane-2007*, Szczecin-Międzyzdroje, 207-212, 2007.
- C2 Bialkiewicz A.: Zagrożenia obiektów sakralnych. *XXX Konferencja Naukowo-Techniczna Awaryjne Budowlane-2022*, 21-32, Szczecin - Międzyzdroje, 2022.
- C3 Błaszczyński T., Oleksiejuk H., Firlei E., Błaszczyński M.: Wielostopniowy monitoring i zabezpieczenie budynków pod ochroną konserwatorską przed awarią lub katastrofą. *XXV Konferencja Naukowo-Techniczna Awaryjne Budowlane-2011*, 395-402, Szczecin - Międzyzdroje, 2011.
- C4 Błaszczyński T., Sielecki P.: Analiza wpływu błędów projektowych i wykonawczych na awarię kamienicy z lat 30-tych XX wieku. *XXIII Konferencja Naukowo-Techniczna Awaryjne Budowlane-2007*, 213-220, Szczecin-Międzyzdroje, 2007.

- C5 Deneka A., Rudziński L., Grochal W.: Adaptacja i modernizacja zabytkowego Spichrza Feuersteina na cele usługowo-handlowe. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 315-324, 1996.
- C6 Drobiec Ł.: Przyczyny awarii i katastrof obiektów zabytkowych. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 33-52, Szczecin - Międzyzdroje, 2022.
- C7 Drobiec Ł.: Przyczyny zniszczeń i sposób remontu murów Bazyliki matki Boskiej Anielskiej w Dąbrowie Górniczej. *Czasopismo Techniczne*, 9, 106, 25-36, Kraków, 2009.
- C8 Eckert W., Chmieliński K.: Przyczyny uszkodzeń i propozycje sposobów wzmocnienia gotyckiego kościoła w Bieniowie. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 291-295, 1996.
- C9 Frasunkiewicz-Puchalska J., Tasarek J.: Nadbudowa i modernizacja zabytkowego budynku bankowo-hotelowego. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 325-332, 1996.
- C10 Gajownik R., Jarmontowicz R., Sieczkowski J.: Diagnostyka i metody oceny bezpieczeństwa konstrukcji murowych. *XXII Ogólnopolska Konferencja Warsztat Pracy Projektant Konstrukcji WPPK-2007*, Szczyrk, 2007.
- C11 Gromysz K.: Remonty wychylonych z pionu Kościoła i domu jednorodzinnego. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 155-161, 1996.
- C12 Hebda L., Czeszyński M., Nikodem D.: Skutki braku odpowiedniego zabezpieczenia budynków zabytkowych w okresie przestoju eksploatacyjnego. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 209-2018, Szczecin - Międzyzdroje, 2022.
- C13 Janowski Z., Hojdys Ł., Krajewski P.: Analiza oraz naprawa i rekonstrukcja sklepień w obiektach historycznych. *XXIII Konferencja Naukowo-Techniczna Awarie Budowlane-2007*, Szczecin-Międzyzdroje, 251-260, 2007.
- C14 Janowski Z., Janowski M.: Awaria zabytkowej hali oraz problemy związane z jej rekonstrukcją. *XXV Konferencja Naukowo-Techniczna Awarie Budowlane-2011*, 427-436, Szczecin-Międzyzdroje, 2011.
- C15 Janowski Z.: Problemy konstrukcyjne związane z odbudową Biblioteki Tynieckiej „Wielkiej Ruiny” w Opactwie Tynieckim. *XXIV Konferencja Naukowo - Techniczna Awarie Budowlane-2009*, 631-642, Szczecin-Międzyzdroje, 2009.
- C16 Kałuża M., Hulimka J., Kubica J.: Stan awaryjny wieży ceglanej w stuletnim budynku uniwersyteckim. *XXVI Konferencja Naukowo-Techniczna Awarie Budowlane-2013*, Szczecin-Międzyzdroje, 159-166, 2013.
- C17 Majewski T., Niedostatkiwicz M.: Diagnostyka cienkościennych żelbetowych sklepień kolebkowych w budynku zabytkowym. Część 1. *Przegląd Budowlany*, Warszawa, 11-12, 2-6, 2022.
- C18 Majewski T., Niedostatkiwicz M.: Diagnostyka cienkościennych żelbetowych sklepień kolebkowych w budynku zabytkowym. Część 2. *Przegląd Budowlany*, Warszawa, 1-2, 122-126, 2023.
- C19 Majewski T., Niedostatkiwicz M.: Uszkodzenia pożarowe dachu budynku kościoła pw. Świętych Apostołów Piotra i Pawła. *Przegląd Budowlany*, Warszawa, 9, 603, 2-6, 2021.
- C20 Malczyk A.: Uszkodzenia i sposoby napraw konstrukcji murowej wież zabytkowej bazyliki. *XXV Konferencja Naukowo-Techniczna Awarie Budowlane-2011*, 477-484, Szczecin-Międzyzdroje, 2011.
- C21 Matysek P., Witkowski M.: Badania wytrzymałości i odkształcalności XIX-wiecznych murów ceglanych. *XXVI Konferencja Naukowo-Techniczna Awarie Budowlane-2013*, Szczecin-Międzyzdroje, 183-190, 2013.
- C22 Minch M., Trochanowski A.: Wybrane zagadnienia wzmocnienia konstrukcji zabytkowego pałacu w Dobrzycy. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 297-306, 1996.
- C23 Mrozowicz J., Gawron K.: Remont budynków czynszowych w historycznej zabudowie śródmiejskiej. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 333-339, 1996.
- C24 Niedostatkiwicz M.: Błędy realizacji prac remontowych przyczyna uszkodzeń wilgotnościowych zabytkowego budynku Sali BHP w Gdańsku. *Builder*, 9, 290, 50-53, Warszawa, 2021.
- C25 Niedostatkiwicz M.: Building modernization located in the conservation protection zone in the aspect of technical conditions. *Inżynieria Bezpieczeństwa Obiektów Antropogenicznych*, 1, 58-74, Warszawa, 2022.
- C26 Niedostatkiwicz M.: Mało znane rozwiązania konstrukcyjne oraz funkcjonalno – użytkowe budynków w powojennej Gdyni. Wybrane przykłady. *Wydawnictwo Bernardinum*, 1-112, Gdynia, 2023.
- C27 Niedostatkiwicz M.: Modernizm w Europie – modernizm w Gdyni. Architektura XX wieku i jej waloryzacja w Gdyni i w Europie: Zagadnienia remontowe modernistycznych budynków mieszkalnych na terenie Działek Leśnych w Gdyni. *Wydawnictwo Miasto Gdynia*, 295-298, Gdynia, 2017.

- C28 Niedostatkiewicz M., Majewski T.: Bazylika pw. Św. Mikołaja w Gdańsku jako przykład monitoringu i diagnostyki zabytkowych obiektów kubaturowych. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 97-122, Cedzyna, 2022.
- C29 Niedostatkiewicz M., Majewski T.: Bunker demolition located in a conservation protection zone in the light of technical, national defense, functional-utility and economic conditions. *Inżynieria Bezpieczeństwa Obiektów Antropogenicznych*, 4, 1-11, Warszawa, 2022.
- C30 Niedostatkiewicz M., Majewski T.: Demolition of the cereal elevator building located in the conservation protection zone in the aspect of technical, functional-utility and economic conditions. *Inżynieria Bezpieczeństwa Obiektów Antropogenicznych*, 3, 55-65, Warszawa, 2022, <https://doi.org/10.37105/iboa.151>.
- C31 Niedostatkiewicz M., Niedostatkiewicz L.: Modernizm w Europie – modernizm w Gdyni. Architektura pierwszej połowy XX wieku i jej ochrona w Gdyni i w Europie: Obiekty – pomniki gdyńskiego tempa budowania okresu powojennego. *Wydawnictwo Miasto Gdynia*, 299-302, Gdynia, 2011.
- C32 Niedostatkiewicz M., Niedostatkiewicz L.: Modernism in Europe – modernism in Gdynia. 20th century architecture until the 1960s and its preservation: The Monuments of Gdynia Post-War Construction Pace. *Wydawnictwo Miasto Gdynia*, 289-291, Gdynia, 2015.
- C33 Niedostatkiewicz M., Niedostatkiewicz L.: Zapomniane konstrukcje młodej Gdyni. *International Workshop City of tomorrow and cultural heritage-Pomerania outlook*, 1, 17-26, Gdańsk, 2005.
- C34 Niedostatkiewicz M., Majewski T., Baryłka A.: Renovation works in buildings in the area of former defensive fortifications. *Inżynieria Bezpieczeństwa Obiektów Antropogenicznych*, 1, 1-21, Warszawa, 2023, <https://doi.org/10.37105/iboa.164>.
- C35 Nowogońska B.: Diagnoza stanu technicznego willi secesyjnej. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 339-346, Szczecin - Międzyzdroje, 2022.
- C36 Ogorzałek A., Żyrek T.: Wzmacnianie fundamentów obiektów historycznych – geotechniczna rutyna czy ekwilibrystyka. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, Wisła, II, 129-156, 2022.
- C37 Owczarek M., Sadowska B., Baryłka A., Kucherowski M.J.: Application of thermal insulating plaster for retrofitting of a building under conservation protection. *Inżynieria Bezpieczeństwa Obiektów Antropogenicznych*, 2, 17-25, Warszawa, 2023, <https://doi.org/10.37105/iboa.172>.
- C38 Paczkowska T., Paczkowski W.: Wzmocnienie elementów konstrukcji nośnej pod zwiększone obciążenia użytkowe. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wrocław-Szklarska Poręba, 141-140, 1996.
- C39 Podhorecki A., Dobiszewska M., Sobczak – Piąstka J., Podhorecki P.: Różne problemy inżynierskie związane z oddziaływaniem budowy wielokubaturowego obiektu budowlanego na istniejące budynki. *XXIII Konferencja Naukowo-Techniczna Awarie Budowlane-2007*, 465-472, Szczecin-Międzyzdroje, 2007.
- C40 Podhorecki A., Dobiszewska M., Sobczak – Piąstka J.: Negatywne skutki źle przygotowanej i prowadzonej budowy w strefie staromiejskiej. *XXV Konferencja Naukowo-Techniczna Awarie Budowlane-2011*, 493-500, Szczecin-Międzyzdroje, 2011.
- C41 Podhorecki A., Sobczak – Piąstka J., Dobiszewska M., Izdebski M.: Diagnostyka zabytkowej synagogi w Bydgoszczy. *XXIV Konferencja Naukowo-Techniczna Awarie Budowlane-2009*, 679-686, Szczecin-Międzyzdroje, 2009.
- C42 Podolski B., Bober W.: Zagrożenia bezpieczeństwa w kwalifikowanych do remontu budynkach starej zabudowy. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wrocław-Szklarska Poręba, 231-236, 1996.
- C43 Radziszewska-Zielina E., Fedorczyk-Cisak M., Steidl T.: Wybrane aspekty diagnostyki i remontu sakralnych obiektów zabytkowych. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 243-254, Szczecin - Międzyzdroje, 2022.
- C44 Rouba B.J.: Zawilgocenie-problem opiekuna Kościoła. *Materiał niepublikowany, przekazany Radzie ds. Kultury i Ochrony Dziedzictwa Kulturowego Konferencji Episkopatu Polski, wersja z roku 2017, uaktualniona w roku 2018 i 2019, Uniwersytet Mikołaja Kopernika w Toruniu*, 1-42, 2017-2019.
- C45 Sekunda R., Szer J.: Awaria i katastrofa budowlana w dwóch remontowanych budynkach. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 255-266, Szczecin - Międzyzdroje, 2022.
- C46 Stawiska N., Stawiski B.: Rewaloryzacja murów w obiektach zabytkowych. *Wiadomości Konserwatorskie*, 11, 18-22, Kraków, 2005.
- C47 Tajchman J., Jurecki A.: Historia technik budowlanych. Fundamenty, rusztowania, mury, więźby, sklepienia. *Wydawnictwo Naukowe PWN SA*, Warszawa 2020.

- C48 Tkacz P.: Ocena wytrzymałości na ściskanie konstrukcji murowych z uwzględnieniem badań in situ-rozprawa doktorska. *Zachodniopomorski Uniwersytet Technologiczny w Szczecinie*, 1-118, Szczecin, 2015.
- C49 Topolnicki M.: Podchwycenie i wzmocnienie fundamentów kościoła św. Jana w Gdańsku metodą iniekcji strumieniowej. *Materiały Międzynarodowego Seminarium CURE „Rewitalizacja budowli miejskich”*, Gdańsk, 17-19.06.2004.
- C50 Trochonowicz M.: Wilgoć w obiektach budowlanych. Problematyka badań wilgotnościowych. *Budownictwo i Architektura*, 7, 131-144-36, Lublin, 2010.
- C51 Wałach D., Jaskowska-Lemańska J., Dybeł P.: Analiza przyczyn powstania uszkodzeń kościoła pod wezwaniem Podwyższenia Krzyża Świętego w Podlegórzcu. *XXIV Konferencja Naukowo-Techniczna Awarie Budowlane-2009*, 239-248, Szczecin - Międzyzdroje, 2009.
- C52 Wałach D., Jaskowska-Lemańska J.: Stan zachowania zabytkowych konstrukcji murowych-studium przypadku. *Builder*, 11, 74-77, Warszawa, 2016.
- C53 Wandzik G., Szojda L., Ajdukiewicz A.: Zabezpieczenie budynków w obszarach ujawniania się nieciągłości deformacji terenu. *XXIII Konferencja Naukowo-Techniczna Awarie Budowlane-2007*, 341-348, Szczecin-Międzyzdroje, 2007.
- C54 Wesołowski M.: Zagrożenia starych budynków w sąsiedztwie nowej zabudowy. *XXIV Konferencja Naukowo-Techniczna Awarie Budowlane-2009*, 721-728, Szczecin-Międzyzdroje, 2009.
- C55 Zgorzelski B., Szer J.: Najczęstsze uszkodzenia w budynkach zabudowy śródmiejskiej Łodzi z lat 1890-1920. *XXX Konferencja Naukowo-Techniczna Awarie Budowlane-2022*, 689-702, Szczecin - Międzyzdroje, 2022.
- D1 Ciesielski R., Kawecki J., Maciąg E.: Ocena wpływu wibracji na budowle i ludzi w budynkach (diagnostyka dynamiczna). *Wydawnictwo Instytutu Techniki Budowlanej*, Warszawa, 1993.
- D2 Ciesielski R.: Ujęcie obliczeniowe oraz ocena wpływu drgań i wstrząsów ze źródeł zewnętrznych na niektóre typy budowli. *Zeszyty Naukowe Politechniki Krakowskiej*, 1, Kraków, 1961.
- D3 Kawecki J.: Diagnostyka dynamiczna konstrukcji zagłębionych w gruncie. *XX Ogólnopolska Konferencja Warsztat Pracy Projektanta Konstrukcji WPPK-2005*, Wisła-Ustroń, 261-272, 2005.
- D4 Kawecki J., Stypuła S.: Błędy w diagnozach dotyczących oceny wpływów dynamicznych na budynki. *XXIII Konferencja Naukowo-Techniczna Awarie Budowlane-2007*, Szczecin-Międzyzdroje, 267-274, 2007,
- D5 Kawecki J., Stypuła K.: Diagnozy a posteriori wpływów drgań drogowych na budynki. *XXIV Konferencja Naukowo-Techniczna Awarie Budowlane-2009*, Szczecin-Międzyzdroje, 539-546, 2009,
- D6 Kawecki J., Stypuła K.: Jeszcze raz o błędach w diagnozach dotyczących oceny wpływów dynamicznych na budynki oraz ludzi w budynkach. *XXVI Konferencja Naukowo-Techniczna Awarie Budowlane-2013*, Szczecin-Międzyzdroje, 2013,
- D7 Kawecki J., Stypuła J.: Naruszenie wymagań dotyczących zapewnienia ludziom w budynku niezbędnego komfortu wibracyjnego jako stan zagrożenia awaryjnego. *Inżynieria i Budownictwo*, Warszawa, 5, 266-269, 2011,
- D8 Kawecki J., Stypuła K.: Zapewnienie komfortu wibracyjnego ludziom w budynkach narażonych na oddziaływanie komunikacyjne. *Wydawnictwo Politechniki Krakowskiej*, Kraków, 2013,
- D9 Kawecki J., Tataro K.: Procedury uwzględniania wpływu drgań komunikacyjnych na budynki eksploatowane. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 123-142, Cedzyna, 2022.
- D10 Runkiewicz L.: Wzmacnianie i zabezpieczanie istniejących obiektów w sąsiedztwie realizowanych budynków plombowych. *Przegląd Budowlany*, 4, 28-38, Warszawa, 2008.
- D11 Runkiewicz L., Sieczkowski J.: Problemy techniczne budowy obiektów na terenie gęstej zabudowy. *Przegląd Budowlany*, 9, 18-23, Warszawa, 2015.
- D12 Wilde K., Rucka M., Chróścielewski J., Niedostatkiwicz M.: Rozwiązanie przegrody wibroizolacyjnej w budynku zabytkowym narażonym na drgania wywołane ruchem kołowym i szynowym. *Inżynieria Morska i Geotechnika*, 5, 408-411, Gdańsk, 2013.
- D13 Instrukcja ITB nr 348/98: Diagnostyka dynamiczna i zabezpieczenia istniejących budynków mieszkalnych przed szkodliwym działaniem drgań na właściwości użytkowe budynków. *Wydawnictwo Instytutu techniki Budowlanej*, Warszawa, 1998.
- D14 Instrukcja ITB nr 376/02: Ochrona zabudowy w sąsiedztwie głębokich wykopów. *Wydawnictwo Instytutu Techniki Budowlanej*, Warszawa, 2002.
- D15 PB-85/B-02170:2016: Ocena szkodliwości drgań przekazywanych przez podłoże na budynki.
- D16 PN-85/B-02171:2017: Ocena wpływu drgań na ludzi w budynkach.
- E1 Gliniecki S.P.: Geotechnika budowlana. *Wydawnictwo Politechniki Białostockiej*, Białystok 2010,

- E2 Godlewski T., Niemyjska M.: Ryzyko geotechniczne w projektowaniu i realizacji głębokich wykopów. *Acta Scientiarum Polonorum, Architectura-Budownictwo*, 17, (3), 27-36, Warszawa, 2018,
- E3 Godlewski T., Koda E., Mitew-Czajewska M.: Geotechniczne oddziaływania obiektów w miejskiej przestrzeni podziemnej. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 97-122, Cedzyna, 2022,
- E4 Koda E., Godlewski T.: Zasady wykonywani ekspertyz geotechnicznych z uwzględnieniem budynków w zabudowie miejskiej. *XVI Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 81-108, Cedzyna, 2018,
- E5 Kumor Ł., Kumor M.: Błędy w rozpoznaniu podłoża i projektowaniu geotechnicznym na przykładzie doświadczeń. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, (wykład), Wisła, 2022,
- E6 Lechowicz Z., Gajewska B., Gajewska K., Wdowska M.: Badania i dobór parametrów podłoża gruntowego do oceny zachowania się budowli. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, I, 255-272, Wisła, 2022,
- E7 Meyer Z., Kowalów M., Chryścina M., Wróbel-Hen M., Wasiluk A.: Analiza parametrów geotechnicznych podłoża na podstawie próbnych obciążeń. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, II, 41-62, Wisła, 2022,
- E8 Niedostatkiewicz M.: Usterki i uszkodzenia budynku mieszkalnego jako następstwo błędów projektowych nowo realizowanego sąsiedniego obiektu budowlanego. *XXIV Konferencja Naukowo-Techniczna Awarie Budowlane-2009*, Szczecin-Międzyzdroje, 671-678, 2009,
- E9 Niedostatkiewicz M., Majewski T.: Uszkodzenia ścian konstrukcyjnych wielorodzinnego budynku mieszkalnego spowodowane błędami projektowymi i wykonawczymi. *XXVII Konferencja Naukowo-Techniczna Awarie Budowlane-2015*, Szczecin-Międzyzdroje, 649-656, 2015,
- E10 Paczkowska T.: Niewłaściwe rozpoznanie podłoża przyczyną awarii obiektów budowlanych. *XXVI Konferencja Naukowo-Techniczna Awarie Budowlane-2013*, Szczecin-Międzyzdroje, 394-400, 2013,
- E11 Popielski P., Majewski T., Bednarz B., Niedostatkiewicz M.: Deformacje filtracyjne i ich oddziaływanie na osiadanie podłoża na przykładzie zabytkowego obiektu sakralnego. *Materiały Budowlane*, Warszawa, 10, 602, 2-6, 2022,
- E12 Majewski T., Popielski P., Niedostatkiewicz M., Mieszkowski R.: Diagnostyka podłoża gruntowego i fundamentów zabytkowego Kościoła w stanie awarii. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, II, 1-40, Wisła, 2022,
- E13 Popielski P., Kasprzak A., Bednarz B.: Wykorzystanie wyników monitoringu geotechnicznego głębokich posadowień do weryfikacji modeli numerycznych parametrów gruntu oraz określenia oddziaływania realizowanej inwestycji na obiekty sąsiednie. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, II, 157-180, Wisła, 2022,
- E14 Sendkowski J., Tkaczyk A., Tkaczyk Ł.: Oddziaływania geotechniczne za zabudowę sąsiednią w świetle analizowanych przypadków. *XVII Konferencja Naukowo-Techniczna Warsztaty Pracy Rzeczoznawcy Budowlanego*, 465-474, Cedzyna, 2022,
- E15 Szypcio Z.: Pewne problemy oddziaływania wody gruntowej na konstrukcje i podłoża gruntowe. *XXXVI Ogólnopolskie Warsztaty Pracy Projektanta Konstrukcji WPPK-2022*, II, 197-210, Wisła, 2022,
- E16 Tarnawski M.: Analiza przypadku osiadań długotrwałych. *XXVIII Konferencja Naukowo-Techniczna Awarie Budowlane-2017*, Szczecin-Międzyzdroje, 587-594, 2017,
- E17 Tarnawski M.: Awarie budowli posadowionych na iłach. *XXVI Konferencja Naukowo-Techniczna Awarie Budowlane-2013*, Szczecin-Międzyzdroje, 442-450, 2013,
- E18 Tarnawski M., Frankowski Z., Godlewski T., Gwizdała K., Kłosiński J., Mieszkowski R., Nowosad A., Saloni J., Słabek J., Szczepański T., Ura M., Wierzbicki J. Wójcik M.: Badania polowe podłoża budowli. *Wydawnictwo Naukowe PWN*, Warszawa, 2020,
- E19 Wandzik G., Szojda L., Ajdukiewicz A.: Zabezpieczenie budynków w obszarach ujawniania się nieciągłości deformacji terenu. *XXIII Konferencja Naukowo-Techniczna Awarie Budowlane-2007*, 341-348, Szczecin-Międzyzdroje, 2007,
- E20 Wiłun Z.: *Zarys geotechniki. Państwowe Wydawnictwo Naukowe*, Warszawa, 1976.
- F1 Jeż J.: Drzewa a stateczność budowli posadowionych na gruntach pęczniejących. *Przegląd budowlany*, Warszawa, 2-3/90, 1990.
- F2 Jeż J.: *Przyrodnicze aspekty bezpiecznego budownictwa. Wydawnictwo Politechniki Poznańskiej*, Poznań, 1998.

- F3 Jeż J., Suwalski J.: Wpływ nieprawidłowego zadrzewienia osiedla na rysowanie się ścian budynków. *VII Konferencja Naukowo-Techniczna Problemy Remontowe w Budownictwie Ogólnym*, Wocław-Szklarska Poręba, 221-229, 1996.
- F4 Jeż J., Wojtasik A.: Wpływ drzew na awarię budynku posadowionego na gruncie pęczniejącym. *Inżynieria i Budownictwo*, Warszawa, 7/89, 1989.
- G1 Jarmakowski A.T., Rybicki A.: 1949 – 1979, 30 lat Parafii Najświętszego Serca Pana Jezusa w Gdyni. Gdynia, 1979.
- G2 Kitowski S.: Gdynia-miasto z morza i marzeń. *Wydawnictwo Alter Ego Sławomir Kitowski*, Gdynia, 2005.
- G3 Sołtysik M.J.: Gdynia miasto dwudziestolecia międzywojennego. Urbanistyka i architektura. *Państwowe Wydawnictwo Naukowe*, Warszawa 1993.
- G4 Sołtysik M.J.: Na styku dwóch epok. Architektura gdyńskich kamienic okresu międzywojennego. *Wydawnictwo Alter Ego Sławomir Kitowski*, Gdynia, 2003.
- N1 PN-EN-1991-1-1: *Oddziaływania na konstrukcje (część 1-5)*.
- N2 PN-EN-1992-1-1: *Reguły ogólne i reguły dla budynków*.
- N3 PN-B-06250:1988: *Beton zwykły*.
- N4 PN-B-03264:2002: *Konstrukcje betonowe, żelbetowe i sprężone. Obliczenia statyczne i projektowanie*.
- N5 PN-EN 1504-(cz. 1-10):2006: *Wyroby i systemy do ochrony i napraw konstrukcji betonowych. Definicje, wymagania, sterowanie jakością i ocena zgodności*.
- N6 PN-74/B-06262: *Metoda sklerometryczna badania wytrzymałości betonu na ściskanie za pomocą młotka Schmidta typu N*.
- N7 PN-EN 14630:2007: *Wyroby i systemy do ochrony i napraw konstrukcji betonowych. Metody badań. Oznaczanie głębokości karbonatyzacji w stwardniałym betonie metodą fenoloftaleinową*.
- N8 Komentarz naukowy do PN-B-03264:2002 *Konstrukcje betonowe, żelbetowe i sprężone. Tom 1 i 2. Wydawnictwo Instytutu Techniki Budowlanej*, Warszawa, 2005.